

Site/Project Location: MP 125 to 125.5 Spread 7-8

Date of Inspection: 26 September 2016

Keitu Inspector: RJS

Report Photo #1 "Topsoil Not Completely Stripped":

46.70342°N 101.29109°W



Report Photo #2 "1+ Foot of Topsoil Not Stripped":

46.70399°N 101.29213°W



Report Photo #3 "1+ Foot of Topsoil Not Stripped":

46.70481°N 101.29340°W



Report Photo #4 "Cutout - Estimate of Topsoil Depth":

47.70°N 101.29°W



Report Photo #5 "Center of ROW - Visible Topsoil Layer":

47.70548°N 101.29469°W



Report Photo #6 “Center of ROW – Visible Topsoil Layer”:

47.70548°N 101.29469°W



Report Photo #7 “Center of ROW – Visible Topsoil Layer”:

47.70548°N 101.29469°W



Report Photo #8 "Center of ROW - Visible Topsoil Layer":

47.70548°N 101.29469°W



Report Photo #9 "Center of ROW - Visible Topsoil Layer":

46.70547°N 101.29477°W



Report Photo #10 “Visible Topsoil Layer Topped w/Subsoil”:

46.70547°N 101.29477°W



Report Photo #11 “Visible Topsoil Layer Topped w/Subsoil”:

46.70547°N 101.29477°W



Report Photo #12 “Visible Topsoil Layer Topped w/Subsoil”:

46.70547°N 101.29477°W



Report Photo #13 “Visible Topsoil Layer Topped w/Subsoil”:

46.70547°N 101.29477°W



Report Photo #14 "Visible Topsoil Layer Topped w/Subsoil":

46.70547°N 101.29477°W

